



Thermography with VARIOSCAN

Building inspection



Insulation defects before reconstruction



Building after reconstruction. Further existing lacks: poorly windows and no insulation of the basement